



Comparison of Services

Description of Work	Option A	Option B	Option C
Renovation			
Excess sticking paint scraped back and sanded Minor areas of rot treated, filled and sanded Weak joints reinforced Meeting rails and stiles aligned Sashes/openers/doors planed and/or built out to fit Defective putty replaced Weights disentangled and rebalanced (sash only) Hinges eased and adjusted (casement, door only) Repairs and Part Replacements	V V V V	\(\frac{1}{\sqrt{2}} \)	- - - - -
	V	V	
New FSC timber sections constructed in-situ to replace major areas of rot New FSC timber like-for-like sashes/openers/doors fitted as required	<i>V</i>	-	-
New glass fitted in place of cracked panes	✓	-	-
New strong (reinforced) traditional waxed cotton sash cords fitted (sash only)	✓	-	-
New Joinery			
New FSC timber joinery preserved, knotted and end grain sealed	✓	✓	✓
New FSC timber joinery double-primed with microporous spray paint	V	V	V
New FSC timber factory-moulded staff beads fitted (sash only) New FSC timber factory-moulded parting beads fitted (sash only)	✓ ✓	✓ ✓	✓
New FSC timber sashes/openers/doors fitted	-	V	V
New FSC timber outer sash box/casement/door frame fitted	-	-	✓
New FSC timber architrave and nosing fitted	-	-	✓
Draught Proofing			
New effective, unobtrusive, wipe-clean draught seals fitted	✓	~	✓
New Opening Mechanisms			
New extra-strong diamond-braided polyester/nylon sash cords fitted (sash only) New weights fitted (sash only) New smooth-running silent ball bearing pulleys fitted (sash only) New smooth-opening silent ball bearing hinges fitted (casement, door only)	-	\(\times \)	\(\sqrt{V} \) \(\sqrt{V} \) \(\sqrt{V} \)
Double Glazing			
New high performance, internally beaded double glazing supplied factory-fitted	-	✓	✓

Description of Work	Option A	Option B	Option C
Achievable Whole-Window U-values			
Best U-values achieved in W/m2K		1.4	1.4
Optional Glass Upgrades			
Optional - New extra-insulating low-e glass fitted Optional - New decorative coloured/textured/leaded glass fitted Optional - New privacy frosted/sandblasted/stencilled glass fitted Optional - New toughened safety glass fitted Optional - New acoustic laminate glass fitted Optional - New security laminate glass fitted Optional - New sunlight and heat reflecting solar control glass fitted Optional - New self cleaning glass fitted	\(\times \) \(\t	\(\times \) \(\t	V V V V
Optional - New ultra-clear low iron glass fitted	✓	✓	✓
New Ironmongery New high quality key-operated security stops/locks/child safety restrictors fitted New high quality window fastener fitted (sash, casement only) New high quality sash lifts fitted (sash only) New high quality sash D-handles fitted (sash only) New high quality window stay fitted (casement only) New high quality 5-lever lock and door knob fitted (door only) New high quality high security door bolts fitted (door only) Making Good Exposed timber primed Adjacent disturbed plasterwork made good (no repainting) Final Painting and Decoration Optional - New joinery fully factory-finished with microporous spray paint Optional - Interior/exterior timber fully hand painted/decorated	\(\frac{\psi}{\psi} \)		V V V V V V V V V V V V V V V V V V V
Optional - Interior/exterior masonry/walls fully hand painted/decorated	✓	✓	V
Project Management			
Work areas protected with dust sheets Work areas vacuumed and glass cleaned on completion Waste removed and disposed of by licensed waste carrier	<i>V V</i>	<i>V V</i>	<i>V V</i>
VAT			
Reduced-rate VAT (5%) applied for draught proofing Standard-rate VAT (20%) applied for all other work	V	✓✓	✓
Guarantee			
Guarantee provided Deposit insurance-backed (no fees) Guarantee insurance-backed (no fees)	1yr - -	5yr - -	10yr
FENSA Certificate			
FENSA Installation Certificate issued on completion	-	-	✓